E043 Flint Creek Enforcement Area

COMMISSIONER REMARK INDEX

Water Right #		Remark
76GJ	133154-00	Diversion cannot be identified. The MOD, source, and POD may be incorrect. Little Gold Creek doesnt extend into the claimed POD location. Diversion placed as claimed.
76GJ	17134-00	THE NATURAL STREAM CHANNEL OF HENDERSON CREEK HAS BEEN DISTURBED DUE TO PLACER MINING IN SEC 29, TWP 9N, RGE 13W. WATER FROM HENDERSON CREEK AND UNDEVELOPED SPRINGS IS COLLECTED BY DRAIN DITCHES AND PONDS LOCATED WITHIN THE LEGAL LAND DESCRIPTIONS DESCRIBED BY POINTS OF DIVERSION 5, 6, AND 7. WATER COLLECTED IN THESE DRAIN DITCHES IS RETURNED TO THE HENDERSON CREEK STREAM CHANNEL AT SEVERAL LOCATIONS WITHIN SEC 29, TWP 9N, RGE 13W. WATER IS ALSO DIVERTED FROM HENDERSON CREEK THROUGH HEADGATE DIVERSIONS DESCRIBED BY POINTS OF DIVERSION 1, 2, 3, AND 4. PODS 5, 6, AND 7 PLACED AS CLAIMED.
76GJ	98883-00	WATER IS DIVERTED FROM FLINT CREEK THROUGH OLD ROLLIER DITCH TO THE SECONDARY POINT(S) OF DIVERSION WHERE MEASURING DEVICES ARE LOCATED. THE OLD ROLLIER DITCH IS LABELED AS FLINT CREEK ON THE USGS TOPOGRAPHIC MAP BUT HAS BEEN HISTORICALLY USED AS A DITCH WITH A HEADGATE TYPE CONTROL STRUCTURE LOCATED AT THE CLAIMED POINT OF DIVERSION.

E043 Flint Creek Enforcement Area

COMMISSIONER REMARK INDEX

Water Right #	Remark