# CHECKLIST ENVIRONMENTAL ASSESSMENT

**Proposed Action:** Approve Drilling Permit (Form 22)

**Project/Well Name:** Dart 21-33 2H **Operator:** Devon Energy Williston, LLC

**State:** Montana

**Location:** SWSW Section 16 T28N R59E

**County:** Roosevelt

Field (or Wildcat): Wildcat

**Proposed Project Date:** 9/1/2025

## I. DESCRIPTION OF ACTION

Triple derrick drilling rig to drill a single lateral horizontal Bakken Formation test, 26,405'MD/10,239'TVD.

## II. PROJECT DEVELOPMENT

# A. PUBLIC INVOLVEMENT, AGENCIES, GROUPS, OR INDIVIDUALS CONTACTED

10 day from public notification opportunity to protest for hearing:

Published in Helena Independent Record on 3/20/2025. Published in Northern Plains Independent on 3/20/2025.

No written demand for hearing has been filed per ARM 36.22.601 as of 3/31/2025.

Montana Bureau of Mines and Geology, GWIC website (Roosevelt County Wells).

US Fish and Wildlife, ENDANGERED, THREATENED, PROPOSED AND CANDIDATE SPECIES MONTANA COUNTIES, Roosevelt County

Montana Natural Heritage Program Website (FWP) Heritage State Rank= S1, S2, S3, T28 R59E

Montana Cadastral Website

Surface Ownership and surface use Section 16 T28N R59E

Montana Department of Natural Resources MEPA Submittal

USDA Natural Resources Conservation Service-Soils Map

## **B. ALTERNATIVES CONSIDERED**

**No Action Alternative:** Permit to drill the well would not be issued by BOGC.

**Action Alternative:** Referred to the BOGC for further environmental review.

#### III. IMPACTS ON THE PHYSICAL ENVIRONMENT

# A. AIR QUALITY

Long drilling time: No, 10-20 days.

Unusually deep drilling (high horsepower rig): No

Emission sources: Vehicles traveling on county road to location, combustion engines on location during drilling operations.

Fugitive dust from traveling operations and location during active drilling.

Possible H2S gas production: Potentially in Mississippian formations.

In/near Class I air quality area: No.

Air quality permit for flaring/venting (if productive): Yes, DEQ air quality permit required under 75-2-211. AQB review.

Comments: No special concerns – Triple derrick drilling rig to drill a single lateral horizontal Bakken Formation test, 26,405'MD/10,239'TVD. If there are no gas gathering systems nearby, associated gas can be flared under Board Rule 36.22.1220.

# **B. WATER QUALITY**

Salt/oil-based mud: Surface casing hole will be drilled with freshwater and freshwater mud system, Rule 36.22.100.1. Will drill with oil-based invert drilling fluids for the intermediate casing hole. Horizontal hole will be drilled with saltwater.

High water table: No

Surface drainage leads to live water: No, closest drainage is an unnamed ephemeral drainage, 1,000' east of location. Drainage leads to confluence of Little Muddy Creek 2.75 miles south of location.

Water well contamination: 1 water well located within ½ mile of location and is considered domestic with a total depth of 200' and static water level of 64' in section 17 T28N R59W.

Porous/permeable soils: Moderate, fine silty loam.

Class I stream drainage: None.

Groundwater vulnerability area: No.

Mitigation:

Lined reserve pit

X Adequate surface casing

Berms/dykes, re-routed drainage

X Closed mud system

X Off-site disposal of solids/liquids (in approved facility)

Other

Comments: Steel surface casing will be run and cemented to surface to protect ground water. (Rule 36.22.1001).

Comments: Surface hole will be drilled with a freshwater mud system to 2000'. Steel surface casing will be run to 2000' and cemented back to surface to protect freshwater zones in adjacent water wells, Rule 36.22.1001. Also, covering Fox Hills aquifer. Adequate surface casing and BOP equipment to prevent problems, (5,000 psi annular and double ram), Rule 36.22.1014.)

# C. SOILS/VEGETATION/LAND USE

Vegetation: Grasslands. Stream crossings: None anticipated. High erosion potential: Slight, cut of 20.5' with fill of 19'.
coss of soil productivity: No, location to be restored after drilling if plugged.
Inusually large wellsite (Describe dimensions): A large well site 430'X 585' required for a four-well ad.
Damage to improvements: Slight, to grassland.
Mitigation  Avoid improvements (topographic tolerance)  Exception location requested  X_ Stockpile topsoil  Stream Crossing Permit (other agency review)  Reclaim unused part of wellsite if productive  Special construction methods to enhance reclamation  access Road: Access will be from CR 1004 to established oilfield road to Duel Trucking. 1500' of new  access road to be built to location in Section 16 T28N R59E.  Drilling fluids/solids: Devon Energy Williston, LLC will not be utilizing a drilling pit. Drilling fluids and olids will be transported to a state approved disposal facility.
D. HEALTH HAZARDS/NOISE
Proximity to public facilities/residences: No occupied structures within a 1/4-mile radius. Closest occupied structure is 1.25 miles away in NWNW Section 28 T28N R59E. The town of Bainville, MT is .25 miles southwest of location on MT Highway 2.
Possibility of H2S: Possibility in Mississippian formations.  Dize of rig/length of drilling time: 5-10 days.  Mitigation:  _X Proper BOP equipment  _ Topographic sound barriers  _ H2S contingency and/or evacuation plan  _ Special equipment/procedures requirements  Other:

# E. WILDLIFE/RECREATION

Sage Grouse: No.

Proximity to sensitive wildlife areas (DFWP identified): None.

Proximity to recreation sites: None.

Creation of new access to wildlife habitat: No. Conflict with game range/refuge management: No.

Threatened or endangered species: Pallid Sturgeon, Sicklefin Chub, Interior Least Tern, Whooping Crane, Piping Plover, Northern Long-eared Bat, Leconte's Sparrow, Bobolink, and Snapping Turtle.

Mitigation:
Avoidance (topographic tolerance/exception)
Other agency review (DFWP, federal agencies, DNRC Trust Lands)
Screening/fencing of pits, drillsite
Other:

Comments: State of Montana Trust Lands is the surface owner. There may be species of concern that maybe impacted by this wellsite. We ask the operator to consult with the surface owner as to what he would like done if a species of concern is discovered at this location. The Board of Oil & Gas has no jurisdiction over state surface lands. State of Monana Trust Lands and Minerals will do surface EA.

## IV. IMPACTS ON THE HUMAN POPULATION

# A. HISTORICAL/CULTURAL/PALEONTOLOGICAL

Proximity to known sites:

Mitigation

- \_\_avoidance (topographic tolerance, location exception)
- \_\_other agency review (SHPO, DNRC Trust Lands, federal agencies)

Other: State of Montana Trust Lands is the surface owner. There may be possible historical/cultural/paleontological sites that may be impacted by this wellsite. We ask the operator to consult with the surface owner as to desires to preserve these sites or not, if they are found during construction of the wellsite. State of Monana Trust Lands and Minerals will do surface EA.

## **B. SOCIAL/ECONOMIC**

Substantial effect on tax base

- \_\_ Create demand for new governmental services
- Population increase or relocation

Comments: No concerns.

#### IV. SUMMARY

No long-term impacts expected. Some short-term impacts will occur, but can be mitigated. I conclude that the approval of the subject Notice of Intent to Drill (does/<u>does not</u>) constitute a major action of state government significantly affecting the quality of the human environment, and (does/<u>does not</u>) require the preparation of an environmental impact statement.

EA Checklist	Name:	Ben Davis	Date:	7/23/2025
Prepared By:	Title:	Technical Program Coordinator		