

Photos of the St. Mary Facilities



Construction on the St. Mary Siphons circa 1906 - 1908



Land preparations for the St. Mary Canal circa 1906 -1908



Maintenance Work on Sherburne Reservoir



St. Mary Diversion Dam



St. Mary Diversion Dam



St. Mary Siphon



2003 leak in St. Mary Siphon where pipe crosses the St. Mary River



Leaks in collar joints of St. Mary Siphon



Section of buckled siphon replaced in 2003



Pipe repair work in 2003



Hall's Coulee Siphon



View of Drop No 4 looking upstream



Eroded concreted and exposed rebar in face of drop structure